



Vk<sub>2</sub> SZ 40 3.0  
K 12.5 5000 K 50

Gipc SZ 50 1.0  
K 9.0 2500 K 40

Lke<sub>3</sub> K 30 0.5  
4.5 900 K 60

Lke<sub>3</sub> K 30 0.5  
4.5 900 K 60

Gksz<sub>3</sub> SZ 40 1.0  
K 4.5 2500 K 40

Lke<sub>3</sub> K 30 0.5  
4.5 900 K 60

K<sub>4</sub> SZ 50 2.0  
K 7.5 1800 K 40

K<sub>6</sub> SZ 25 0.5  
K 7.5 1800 K 60

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50

Lk<sub>2</sub> K 40 K 1.0  
4.5 K 800 K 50